

人工造林區及原始林區 (forest plantation & primary forest) ～崩場地整治 Forest Plantation & Primary Forest: Landslide Remediation

【內文 Content】

本步道 (探索覓徑) 位於未經擾動之原始林 (右側林區), 樟樹、血藤、台灣魚藤、刺杜密、觀音座蓮等, 來此可體驗豐富之生態資源。其左側為二八甲崩塌人工造林區, 透過坡頂截排水、坡面縱橫向排水、平台階段、山邊溝、全面植草覆蓋、植生造林等水土保持處理已達到減災效果, 並逐漸恢復既有林木覆蓋。其造林樹種如台灣欒樹、烏心石、臺灣檫、桃花心木、樟樹、臺灣肖楠、水黃皮、大葉楠等, 已逐漸恢復原有之生態。

This trail (Exploration Path) is located within an undisturbed primary forest (the forest area on the right), featuring species such as Camphor trees, Blood Vines, Taiwan Millettia, Spiny-leaved Spurge, and Angiopteris ferns, offering visitors a rich ecological experience. To the left is the "Er-Ba-Jia" landslide reforestation area. Through soil and water conservation treatments—including hilltop interception drainage, vertical and horizontal surface drainage, bench terracing, hillside ditches, full grass coverage, and vegetative reforestation—disaster mitigation has been achieved, and the forest cover is gradually recovering. Plantation species such as Taiwan Golden Rain Trees, Formosan Michelia, Taiwan Zelkova, Mahogany, Camphor trees, Taiwan Incense Cedar, Pongamia, and Large-leaved Machilus are successfully restoring the original ecosystem.

【圖表標註 Diagram Labels】

人工造林區及原始林區分界 Boundary between Forest Plantation and Primary Forest

現在位置 (圖中紅點) You Are Here (Red dot in the image)